

Inspection Photos

April 18, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 335300

Location Name: Brynildson-66S92W /20SWSW

Inspection Document #: 702800139

Garfield County, CO

SWSW Section 20 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Brynildson-66S92W /20SWSW
Location ID: 335300



4/18/22
+39.507812,-107.697760

Photo 1. Photo taken from the Location entrance facing southwest shows an overview of the Location.



Inspection Photos
Location Name: Brynildson-66S92W /20SWSW
Location ID: 335300



Photo 2. Photo taken from the north of the Location facing southwest shows the northwestern interim area colonized by seeded perennial grasses, occasional rabbitbrush and sagebrush, and undesirable plant species/weeds.



Photo 3. Refer to Photo 2 comment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800139

Inspection Photos
Location Name: Brynildson-66S92W /20SWSW
Location ID: 335300



Photo 4. Photo taken from the north of the Location facing southwest shows interim areas (left) and undisturbed areas (right).



Photo 5. Refer to Photo 4 comment.

Inspection Photos
Location Name: Brynildson-66S92W /20SWSW
Location ID: 335300



Photo 6. Photo taken from the southeast of the Location facing northwest shows the interim area colonized by seeded perennial grasses, occasional rabbitbrush and sagebrush, and undesirable plant species/weeds.



Photo 7. Photo taken from the southeast of the Location facing north. Refer to additional comments under Photo 6.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800139

Inspection Photos
Location Name: Brynildson-66S92W /20SWSW
Location ID: 335300



Photo 8. Photo taken from the south of the Location facing northeast shows a river rock lined sediment trap outlet.



Photo 9. Photo taken from the south of the Location facing southwest shows a sediment trap which leads into a river rock lined outlet.

Inspection Photos

Location Name: Brynildson-66S92W /20SWSW

Location ID: 335300



Photo 10. Photo taken from the south of the Location facing northeast shows pedestal formations due to stormwater degradation at a sediment trap outlet.



Photo 11. Refer to Photo 10 comment.

Inspection Photos
Location Name: Brynildson-66S92W /20SWSW
Location ID: 335300



Photo 12. Photo taken from the south of the working pad area facing north shows signs of lack of stabilization BMPs in some areas (rutting is present) .

