



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Bradenhead # 1

Comment: Plumbed to surface

Corrective Action:

Date: \_\_\_\_\_

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Ancillary equipment # 1

Comment: automation

Corrective Action:

Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Flaring:**

Type

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 267403 Type: WELL API Number: 123-21420 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 08/30/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: Water

End Surf Csg Pressure: --

Comment: Plumbed to surface

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<u>At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were warm, clear, calm.</u>	<u>medinaj</u>	<u>04/20/2022</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
<u>699503878</u>	<u>Inspection pictues</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5729290</u>