

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/19/2022

Submitted Date:

04/19/2022

Document Number:

699804398

FIELD INSPECTION FORM

Loc ID 334996 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297605	WELL	PR	01/23/2009	GW	045-16888	SAVAGE 20-16BB (PP20)	PR
297664	WELL	PR	01/10/2009	GW	045-16910	SAVAGE 20-9BB (PP20)	PR
297665	WELL	PR	01/23/2009	GW	045-16911	SAVAGE 20-16 (PP20)	PR
297666	WELL	PR	01/10/2009	GW	045-16912	SAVAGE 20-15(PP20)	PR
297667	WELL	PR	01/10/2009	GW	045-16913	SAVAGE 20-15BB (PP20)	PR

General Comment:

OGCC Inspection Report Summary
On Monday 4/18/22 at approximately 13:30 hours, I, Inspector Corey De Paolo,
Conducted a follow up inspection at CAERUS PICEANCE LLC SAVAGE-67S95W /20SESE.
Location #334996 in Garfield County Colorado.
Refer to document #699803975 inspection conducted on 1/6/22. Previous corrective actions have not been completed.
While there, I observed normal production operations.
During this inspection the following compliance issues were observed:

1) No battery sign located at the tank battery with a previous corrective action date of 9/11/21.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the
Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign located at the tank battery.		
Corrective Action:	A permanent, conspicuous sign will be located at the tank battery.		Date: 09/11/2021
Emergency Contact Number:			
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:		Date:	
Equipment:			
			corrective date
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Pressure transducer located on braden head. All braden head valves are accessible		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Summit midstream		
Corrective Action:			Date:
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities									
Facility ID:	297605	Type:	WELL	API Number:	045-16888	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297664	Type:	WELL	API Number:	045-16910	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297665	Type:	WELL	API Number:	045-16911	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297666	Type:	WELL	API Number:	045-16912	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297667	Type:	WELL	API Number:	045-16913	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams				
		Ditches				
		Culverts				
Compaction						
Berms						
		Check Dams				
Ditches						
		Berms				
Gravel						
		Sediment Traps				
Sediment Traps						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Signs/Markers for corrective actions.	depaoloc	04/19/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804399	Photos for Insp. #699804398	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5729871