

Inspection Photos
Location Name: Federal Wildhorse #15-31
Location ID: 322954



Photo 1 – Photo taken from the entrance of the well location, facing North. Photo illustrates the Operator has failed to perform final reclamation activities.



Photo 2 – Photo taken from the well location. Photo illustrates the Operator has failed to perform final reclamation activities and failed to respond to the previous corrective action inspection.



Inspection Photos
Location Name: Federal Wildhorse #15-31
Location ID: 322954



Photo 3 – Photo taken from the well location. Photo illustrates the Operator has failed to perform final reclamation activities and failed to respond to the previous corrective action inspection.



Photo 4 – Photo taken from the well location, facing East. Photo illustrates the Operator has failed to perform final reclamation activities.



Inspection Photos
Location Name: Federal Wildhorse #15-31
Location ID: 322954



Photo 5 – Photo taken from the associated offsite tank battery, facing North. Photo illustrates the Operator has failed to perform final reclamation activities.



Photo 6 – Photo taken from the associated offsite tank battery. Photo illustrates the Operator has failed to perform final reclamation activities to remove all culverts.



Inspection Photos
Location Name: Federal Wildhorse #15-31
Location ID: 322954



Photo 7 – Photo taken from the associated offsite tank battery, facing North. Photo illustrates the Operator has failed to perform final reclamation activities to remove all equipment.



Photo 8 – 2019 aerial imagery using COGCC GISOnline illustrates the well location and the associated offsite tank battery location.

