

**CHEVRON USA INC
FEE-62N102W 17SWSE
Location # 316644**



Deep ruts on location are sign of lack of compaction

**CHEVRON USA INC
FEE-62N102W 17SWSE
Location # 316644**



Deep ruts on location are sign of lack of compaction

Deep ruts on location are sign of lack of compaction