

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



Photo #6484 from entrance to location.



Photo #6485 from entrance to location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6486 from entrance to location.**

**Photo #6487 Combustor fire.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6488 Charred combustor pad indicates the fire was caused by fluid carry over.**



**Photo #6489 combustor fire.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6490 Burned Pro Fire ignition controller.**



**Photo #6491 Melted automation lines.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6525 Tank appears to have been over pressured and is disconnected.**



**Photo #6526 Tank appears to have been over pressured and is disconnected.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



Photo #6519 No battery sign located at the tank battery.



Photo #6530 Nearest sign to location located approximately 400 yards form location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6512 Multiple places with trash on location.**



**Photo #6513 Multiple places with trash on location.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



Photo #6514 Multiple places with trash on location.



Photo #6518 Multiple places with trash on location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6492 Multiple places with stored and unused equipment.**



**Photo #6493 Multiple places with stored and unused equipment.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6496 Multiple places with stored and unused equipment.**



**Photo #6501 Multiple places with stored and unused equipment.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6508** Multiple places with stored and unused equipment.



**Photo #6494** Loadline open ended.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



Photo #6495 Loadline open ended.



Photo #6497 Loadline open ended.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



Photo #6503 Loadline open ended.



Photo #6505 Loadline open ended.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6504 Bird protector insufficient.**



**Photo #6499 Oily fluid located throughout containment.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6500 Oily fluid located throughout containment.**



**Photo #6506 Oily fluid located throughout containment.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6507 Oily fluid located throughout containment.**



**Photo #6509 Insufficient spill prevention BMP.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6510 Drain valve on produced water transfer pump appears to be leaking.**



**Photo #5611 Insufficient secondary containment and potentially impacted soil under tarp.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6527 Potentially impacted soils continued.**



**Photo #6515 Multiple places with debris.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6521 Multiple places with debris.**



**Photo #6516 Multiple places with trash and debris on location.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6522 Multiple piles of sediment without BMP implementation.**



**Photo #6523 Sediment has been transported on to reclaimed area.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /N23-697

Location ID: 448427



**Photo #6528** Sediment has been transported on to reclaimed area.

**Photo #6524** Sediment has been transported on to reclaimed area.