

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/19/2022

Submitted Date:

04/20/2022

Document Number:

695106134

FIELD INSPECTION FORMLoc ID 307422 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------------|--------------|----------------------------|---------------------------------|
| Distribution, Evergreen | 719-846-7898 | cogcc.evergreen@enrllc.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 112903 | PIT | AC | 09/23/1999 | | - | LAZY LIZARD 11-4 | AC |
| 217643 | WELL | PR | 05/29/1997 | GW | 071-06422 | LAZY LIZARD 11-4 | PR |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

PRIME MOVER IS INSIDE A SHED THAT THE TIN ROOF AS STARTING TO BE TORN IN SPOTS AND COMMING OFF DUE TO WIND. ROOF ON SHED NEEDS TO BE ADDRESSED SOON.

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

IS ACCESSABLE

Corrective Action:

Date:

Type: Progressive Cavity

1

Comment:

NOTE THE PACKING IS NOT LEAKING AT TIME OF INSPECTION BUT THERE IS EVIDENCE BOTH ON THE GROUND AND PAST INSPECTIONS THAT THIS HAS BEEN AN ONGOING PROBLEM WITH THIS WELL.

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 112903 Type: PIT API Number: - Status: AC Insp. Status: ACFacility ID: 217643 Type: WELL API Number: 071-06422 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 11/15/2011 Annual Brhd Completed? Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: approved form 4 on file doc #400682149

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |
| Compaction | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: YESPit ID: 112903Lat: 37.205499Long: -104.682464Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: AdequateComment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: NONECorrective Action: Date: Anchor Trench Present: YESOil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action: Date: **COGCC Comments**

| Comment | User | Date |
|--|----------|------------|
| THIS IS A FOLLOW UP TO INSP. DOC #695105779 CA HAS BEEN ADDRESSED. NOTE THERE IS SOME SALTY BUILD UP ON LOCATION THAT NEEDS TO BE TREATED AS NON E&P WASTE. IN THE FUTURE THIS WILL COME WITH A CORRECTIVE ACTION. | beardslt | 04/20/2022 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------|---|
| 695106135 | INSP. PHOTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5732116 |