

Inspection Photos
Location Name: Knight B #1
API: 05-067-07842



Knight B #1 pump jack and well head.



Well head is stained and wet. Surrounding gravel is stained.

Inspection Photos
Location Name: Knight B #1
API: 05-067-07842



Containment for prime mover exhaust is almost full of fluids.



Apparent point source of Spill/Release Point ID #481990.

Inspection Photos
Location Name: Knight B #1
API: 05-067-07842



**Leaking water line valve on separator resulting in
Spill/Release Point ID #481990.**



**Terminus of observable impacts from Spill/Release Point ID
#481990.**