

Inspection Photos
Location Name: Knight D #2M
API: 05-067-06325



Knight D #2M location photo.



Stained soil next to OilLift pump controller.

Inspection Photos
Location Name: Knight D #2M
API: 05-067-06325



Well head and surrounding area are wet and stained.



95 bbl. produced water PBV.