

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/21/2022

Submitted Date:

04/22/2022

Document Number:

688801162

## FIELD INSPECTION FORM

 Loc ID 325406 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

1 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		sjninspections@ikavenergy.com	All Inspections
Beebe, Sabre		sabre.beebe@ikavenergy.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214721	WELL	PR	08/01/2020	GW	067-06325	KNIGHT D 2M	EI

**General Comment:**

On April 21, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC Knight D #2M. For the most recent field inspection report of this facility, please refer to document #685305055.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Free standing sign near PBV.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Lube Oil	WELLHEAD	<= 1 bbl	
Comment:	Well head and surrounding area are wet and stained. Soil next to OilLift pump controller is stained.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: <u>05/23/2022</u>

In Containment: No	
Comment:	
<input checked="" type="checkbox"/> Multiple Spills and Releases?	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	OilLift pump controller		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Linear rod pump		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 1		

Comment:	Only one marker was observed during this inspection.		Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 2			
Comment:	Telemetry equipment		Date:	
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.019812,-107.637950
Comment:					Date:
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl.
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
067-06325

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No		Date:
Comment:		
Corrective Action:		

**Flaring:**

Type		Date:
Comment:		
Corrective Action:		

**Inspected Facilities**

Facility ID: 214721 Type: WELL API Number: 067-06325 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
On April 21, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC Knight D #2M. For the most recent field inspection report of this facility, please refer to document #685305055. Stained soil was observed next to the OilLift pump controller. The well head and surrounding area are wet and stained.	hughesjo	04/22/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801163	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5732807">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5732807</a>