

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/21/2022

Submitted Date:

04/22/2022

Document Number:

688801160

FIELD INSPECTION FORM

 Loc ID 326340 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
		sjninspections@ikavenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216261	WELL	PR	08/01/2017	GW	067-07867	KNIGHT C 1	EI

General Comment:

On April 21, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC Knight C #1. For the most recent field inspection report of this facility, please refer to document #680603190.

Location				
Lease Road:				
	Type Access			
	comment:			
	Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
	Type WELLHEAD			
	Comment: Free standing sign near location entrance.			
	Corrective Action:			Date:
Emergency Contact Number:				
	Comment: Posted on location sign.			
	Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type SEPARATOR			
	Comment: Stock panel enclosures around all production equipment on location.			
	Corrective Action:			Date:
	Type WELLHEAD			
	Comment: Stock panel enclosure.			
	Corrective Action:			Date:
Equipment:				
Type: Bird Protectors	# 1			corrective date
	Comment:			
	Corrective Action:			Date:
Type: Vertical Heated Separator	# 1			
	Comment:			
	Corrective Action:			Date:
Type: Deadman # & Marked	# 4			
	Comment: SE marker is down.			
	Corrective Action:			Date:
Type: Ancillary equipment	# 1			
	Comment: Telemetry equipment.			
	Corrective Action:			Date:

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 216261 Type: WELL API Number: 067-07867 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On April 21, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC Knight C #1. For the most recent field inspection report of this facility, please refer to document #680603190. During this inspection it was observed that the SE rig anchor marker had been knocked over. No environmental issues were observed during this inspection.</p>	hughesjo	04/22/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801161	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5732798