

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/14/2022

Submitted Date:

04/18/2022

Document Number:

700600382

FIELD INSPECTION FORM

Loc ID 428334 Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16520
Name of Operator: CHEMCO INC
Address: 6970 SOUTH HOLLY CIR STE 206
City: CENTENNIAL State: CO Zip: 80112

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|--------------|-------------------------------|---------|
| Neher, Morgan | 303-771-7777 | morgan@chemco-og.com | |
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |
| Neher, Gray | | gh.neher@chemco-og.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------------------|--------|-------------|------------|---------|-------------------------------|-------------|
| 480899 | SPILL OR RELEASE | AC | 10/25/2021 | | - | Lincoln Disposal Tank Battery | EI |

General Comment:

Improper abandonment of flowline or crude oil transfer line (not purged, depressurized, risers cut 3' below grade, ends sealed, equipment removed) per 1105. Disconnected flowline risers not OOSLAT (out of service locks and tags).

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | OTHER | | |
| Comment: | Improper abandonment of flowline or crude oil transfer line (not purged, depressurized, risers cut 3' below grade, ends sealed, equipment removed) per 1105. Disconnected flowline risers not OOSLAT (out of service locks and tags). | | |
| Corrective Action: | Complete flowline and crude oil transfer line abandonments to comply with Rule 1105. 24 hrs to OOSLAT; 30 Days to complete abandonments per 1105 | Date: | 04/19/2022 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 480899 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403019090 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5726527 |
| 700600383 | Photo 1 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5726521 |
| 700600384 | Photo 2 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5726522 |