

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/21/2022

Submitted Date:

04/22/2022

Document Number:

701004913

**FIELD INSPECTION FORM**

Loc ID 414261 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414255	WELL	PR	08/01/2019	GW	125-11718	SUMAN-GEORGE TRUSTS 31-34	PR

**General Comment:**

Routine Inspection

**Location**

<b>Lease Road:</b>			
	Type Access		
	comment: Trail through pasture		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type WELLHEAD		
	Comment: Lease sign by unit		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
	Comment:		
	Corrective Action:		Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type PUMP JACK		
	Comment: Metal panels around unit, wellhead, VGS and meter run		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Vertical Separator	# 1		
	Comment: Vertical gas separator 50% buried by meter run		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
	Comment:		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
	Comment: Electric panel and telemetry equipment		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
	Comment:		
Corrective Action:			Date:
Type: Pump Jack	# 1		
	Comment: Weatherford unit		
Corrective Action:			Date:

Type: Prime Mover	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 414255 Type: WELL API Number: 125-11718 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701004932	location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5733495">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5733495</a>