

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/21/2022

Submitted Date:

04/22/2022

Document Number:

701004915

FIELD INSPECTION FORM

Loc ID 415051 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415245	WELL	PR	08/01/2019	GW	125-11731	SUMAN-GEORGE TRUSTS 41-34	PR

General Comment:

Routine Inspection

Location

Lease Road:			
	Type Access		
	comment: Trail through pasture		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
	Comment: Lease sign by unit		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:		
	Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type PUMP JACK		
	Comment: Metal panels around unit, wellhead, VGS and meter run		
Corrective Action:			Date:

Equipment:			corrective date
Type: Vertical Separator	# 1		
	Comment: Vertical gas separator 50% buried by meter run		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
	Comment:		
Corrective Action:			Date:
Type: Pump Jack	# 1		
	Comment: Weatherford unit		
Corrective Action:			Date:
Type: Prime Mover	# 1		
	Comment: Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
	Comment: Electric panel and telemetry equipment		
Corrective Action:			Date:

Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 415245 Type: WELL API Number: 125-11731 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701004930	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5733497