

Well Name: Carpenter 32-6-3 2/Carpenter 32-6-3 15 **Location ID** 438700
Document Number: 693904074
Inspector: Catherine Roy
Revegetation is progressing within portions of the interim reclamation areas, and remains sparse/bare in other portions. Specifically areas on well pad berms, down-slope from eastern berms, and cut-slopes support little desirable vegetation.

Correction Action Due: 4/14/2022
Action Taken: Seeded and hydromulched berms and cut slopes

Corrective Action: Bare soils in the project area are not stabilized. Stormwater BMPs (wattles) are degraded and no longer functioning.

Correction Action Due: 5/1/2022
Action Completed: 4/14/2022
Corrective Action: Seeded and hydromulched berms and cut slopes/bare soil areas

