

Inspection Photos  
Operator: Kinder Morgan  
API: 083-06574  
Date: 4/21/2022



Photo 1. View of the project area from the well pad entrance facing center.




Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with rubber rabbitbrush (*Chrysothamnus nauseosus*), crested wheatgrass (*Agropyron smithii*), western wheatgrass (*Pascopyrum smithii*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the eastern project area from the southeastern corner facing northward.





**Russian knapweeds**

Photo 4. View of Russian knapweeds within the interim reclamation area. Scattered individuals observed, (~25) additional weeds may be present as it is early in the growing season.





Photo 5. View of reference area comprised of pinyon and juniper woodland with sagebrush (*Artemisia tridentata*), snakeweed (*Guiterrezia sarothrae*), Indian ricegrass (*Achnatherum hymenioides*), and muttongrass (*Poa fendleriana*).