

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/22/2022

Submitted Date:

04/26/2022

Document Number:

698100253

FIELD INSPECTION FORM

Loc ID 335573	Inspector Name: Arauza, Steven	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 5 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Trujillo, Aaron		aaron.trujillo@state.co.us	
,		COGCC.inspections@caerusoilandgas.com	All Inspections
Rollins, Blair		brollins@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274028	WELL	PR	04/12/2005	GW	045-10314	N. PARACHUTE EF07D H29 595	EI
282093	WELL	PR	02/01/2014	GW	045-11655	N.PARACHUTE EF 16B G29 595	EI
282099	WELL	PR	11/13/2006	GW	045-11653	N.PARACHUTE EF 16D G29 595	EI
282100	WELL	PR	11/09/2006	GW	045-11652	N.PARACHUTE EF01B G29 595	EI
282101	WELL	PR	11/13/2006	GW	045-11651	N.PARACHUTE EF09B G29 595	EI
282108	WELL	PR	09/20/2006	GW	045-11661	N. PARACHUTE EF06D G29 595	EI
282109	WELL	PR	09/21/2006	GW	045-11660	N. PARACHUTE EF07B G29 595	EI
282110	WELL	PR	12/14/2005	GW	045-11659	N.PARACHUTE EF 15B G29 595	EI
282111	WELL	PR	11/09/2006	GW	045-11658	N.PARACHUTE EF 15D G29 595	EI
282112	WELL	PR	12/14/2005	GW	045-11657	N.PARACHUTE EF 14D G29 595	EI
282113	WELL	PR	11/09/2006	GW	045-11656	N PARACHUTE EF02B-32 G29 595	EI
282134	WELL	PR	08/20/2006	GW	045-11679	N.PARACHUTE EF 10B G29 595	EI

282135	WELL	PR	08/23/2006	GW	045-11680	N.PARACHUTE EF11D G29 595	EI
289622	WELL	PR	08/26/2008	GW	045-13844	N.PARACHUTE EF02D G29 595	EI
289623	WELL	PR	08/26/2008	GW	045-13843	N.PARACHUTE EF08D G29 595	EI
289624	WELL	PR	08/26/2008	GW	045-13842	N.PARACHUTE EF08B G29 595	EI
289625	WELL	PR	08/10/2008	GW	045-13841	N.PARACHUTE EF03B G29 595	EI
289626	WELL	PR	03/07/2007	GW	045-13840	N. PARACHUTE EF10D G29 595	EI
289627	WELL	PR	02/01/2014	GW	045-13839	N.PARACHUTE EF09D G29 595	EI
289628	WELL	PR	08/15/2008	GW	045-13838	N.PARACHUTE EF02B G29 595	EI
291027	WELL	PR	08/26/2008	GW	045-14260	N.PARACHUTE EF 12B G29 595	EI
335573	LOCATION	AC	02/01/2014		-	N. Parachute EF G29 595	EI
419810	WELL	PR	08/12/2011	GW	045-20025	N. Parachute DH05-20 G29 595	EI

General Comment:

Joint COGCC environmental inspection with Reclamation Specialist A. Trujillo. Follow-up to Remediation Project #18188. Weather conditions during inspection were cloudy with a temperature of 64 degrees Fahrenheit.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Separator	# 2		corrective date
Comment:	BMPs observed at the two (2) mobile separator units inadequate to contain a spill. See attached photo document.		
Corrective Action:	Install or maintain spill prevention and/or containment BMPs		Date: 04/30/2022

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Fluids inside of secondary containment, see photos.			
Corrective Action:	Remove and properly dispose of fluids to prevent tank corrosion. Inspect and maintain secondary containment to prevent stormwater accumulation following precipitation events.			Date: 05/03/2022

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>274028</u>	Type: <u>WELL</u>	API Number: <u>045-10314</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>282093</u>	Type: <u>WELL</u>	API Number: <u>045-11655</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>282099</u>	Type: <u>WELL</u>	API Number: <u>045-11653</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>282100</u>	Type: <u>WELL</u>	API Number: <u>045-11652</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>282101</u>	Type: <u>WELL</u>	API Number: <u>045-11651</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>282108</u>	Type: <u>WELL</u>	API Number: <u>045-11661</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>282109</u>	Type: <u>WELL</u>	API Number: <u>045-11660</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>282110</u>	Type: <u>WELL</u>	API Number: <u>045-11659</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>282111</u>	Type: <u>WELL</u>	API Number: <u>045-11658</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>282112</u>	Type: <u>WELL</u>	API Number: <u>045-11657</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>282113</u>	Type: <u>WELL</u>	API Number: <u>045-11656</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>282134</u>	Type: <u>WELL</u>	API Number: <u>045-11679</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>282135</u>	Type: <u>WELL</u>	API Number: <u>045-11680</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>289622</u>	Type: <u>WELL</u>	API Number: <u>045-13844</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>289623</u>	Type: <u>WELL</u>	API Number: <u>045-13843</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>289624</u>	Type: <u>WELL</u>	API Number: <u>045-13842</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>289625</u>	Type: <u>WELL</u>	API Number: <u>045-13841</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>289626</u>	Type: <u>WELL</u>	API Number: <u>045-13840</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>289627</u>	Type: <u>WELL</u>	API Number: <u>045-13839</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>

Inspector Name: Arauza, Steven

Facility ID:	289628	Type:	WELL	API Number:	045-13838	Status:	PR	Insp. Status:	EI
Facility ID:	291027	Type:	WELL	API Number:	045-14260	Status:	PR	Insp. Status:	EI
Facility ID:	335573	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	419810	Type:	WELL	API Number:	045-20025	Status:	PR	Insp. Status:	EI

Environmental**Spill/Remediation:**

Comment: This pad is subject to Remediation Project #18188. The Initial F27, doc #402645103, was approved on 5/20/2021 for removal of cuttings from their current location and placement on the pad working surface to acquire a complete analytical data set. As of 4/22/2022 inspection date, the workplan does not appear to have been implemented, as conditionally approved by the COGCC.

Corrective Action: Submit project update during Q2 of 2022 to provide revised implementation schedule, per Rule 913.d.

Any land treatment plans shall comply with COGCC Land Treatment requirements outlined in Rule 905.e.(2).

Date: 06/30/2022

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
698100256	20220422 field photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735030