

Inspection Photos

April 21, 2022

Operator: Caerus Piceance LLC- #10456

Location ID: 334892

Location Name: Shideler-66S92W /32SWNE

Inspection Document #: 702800148

Garfield County, CO

SWNE Section 32 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334892



Photo 1. Photo taken from the south of the Location shows an overview of the Location.



Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334892



Photo 2. Photo taken from the separator at the northeast of the Location shows inadequate protection of an excavated area from entrance by wildlife, livestock or personnel.



Photo 3. Refer to Photo 2 comments.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800148

Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334892



Photo 4. Photo taken from the southeast of the Location facing east shows an unmarked anchor. Photo also shows interim areas dominated by bare ground, undesirable plant species/weeds and shrubs which are not uniform in distribution. Note: GPS coordinates in the photo are slightly off due to phone GPS malfunction/inaccuracy. This photo was taken standing on the southeast of the working pad area.

Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334892



Photo 5. Photo taken from the ditch to the east of the Location shows the establishment of salt cedar, a CO list B Noxious Weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800148

Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334892



Photo 6. Photo taken from the northwest of the Location shows interim areas dominated by shrubs, bare ground and undesirable plant species/weeds. The grass in the photo is annual wheatgrass, an introduced weed.



Photo 7. Refer to Photo 6 comment.



Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334892



Photo 8. Photo taken from the southwest of the Location shows interim areas dominated by shrubs, bare ground and undesirable plant species/weeds. The grass in the foreground is intermediate wheatgrass, a commonly seeded species which is very rare in the interim areas.



Photo 9. Photo taken from the southeast of the Location facing west shows rill erosion occurring in interim areas dominated by bare ground. Shrubs present do not appear sufficient to stabilize soils. Note: GPS coordinates in the photo are slightly off due to phone GPS malfunction/inaccuracy. This photo was taken standing on the southeast of the working pad area.

Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334892



Photo 10. Photo taken from the north of the Location facing south shows erosion occurring in interim areas dominated by bare ground. Shrubs present do not appear sufficient to stabilize soils.



Photo 11. Refer to Photo 10 comment. The grass in the photo is annual wheatgrass, an introduced weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800148

Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334892



Photo 12. Photo taken from the north of the Location facing east shows erosion occurring in interim areas dominated by bare ground. Shrubs present do not appear sufficient to stabilize soils. The grass in the photo is annual wheatgrass, an introduced weed.



Photo 13. Refer to Photo 12 comment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800148