

Inspection Photos

API: 061-06433

Operator: STRACHAN EXPLORATION

Inspection Date: 4/25/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06433 | Date: 4/25/2022

Inspection Photos



Photo 1. Facing south along the former access road. The road has not been recontoured and soils remain compacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06433 | Date: 4/25/2022

Inspection Photos



Photo 2. The ag equipment scrap over the compacted soils on the access road. Soils must be decompacted by cross ripping to at least 18 inches.



Photo 3. The shovel could not penetrate the soils along the access road. Soils must be decompacted by cross ripping to at least 18 inches.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing south toward the abandoned well site located in cropland. There were some areas where soils were ripped and other area that were not.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06433 | Date: 4/25/2022

Inspection Photos



Photo 5. Facing north at the location. Soils were ripped in one direction at some areas (yellow circle) however, other areas remain compacted (blue circle).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06433 | Date: 4/25/2022

Inspection Photos



Photo 6. There are undesirable weeds sprouting up at the location. All undesirable weeds need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06433 | Date: 4/25/2022

Inspection Photos



Photo 7. There are chunks of soil that have not been adequately tilled to establish a proper seed bed.



Photo 8. The shovel could not penetrate some areas of soil at the location. Soils must be decompacted by cross ripping to at least 18 inches.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources