

Inspection Photos

4/22/2022

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 335822

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335822



Photo 1: Photo taken from the location, facing north. Photo provides overview of the northern interim areas of the Location and the perimeter stormwater ditch. Operator appears to have implemented hydromulch (yellow arrow) at slopes, however BMP has not been maintained in a proper functioning condition to minimize erosion, degradation, and to stabilize the slopes; erosion and degradation to the slopes have persisted (red arrow example).

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335822



Photo 2: Photo taken from the northern interim areas of the Location. Photo example showing hydromulch (yellow arrow) that appears to have been implemented by Operator; BMP has not been maintained in a proper functioning condition to minimize erosion, degradation, and to stabilize the slopes; erosion, degradation and stabilization issues have persisted.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335822



Photo 3: Photo taken from the northern interim areas of the Location. Photo example showing hydromulch (yellow arrow) that appears to have been implemented by Operator; BMP has not been maintained in a proper functioning condition to minimize erosion, degradation, and to stabilize the slopes; erosion, degradation and stabilization issues have persisted (red arrow).

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335822



Photo 4: Photo taken from the northern interim areas of the Location. Photo example showing BMPs along slopes have not been maintained in a proper functioning condition to minimize erosion, degradation, and to stabilize the slopes; erosion, degradation and stabilization issues have persisted.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335822



Photo 5: Photo taken from the northern interim areas of the Location. Photo example showing BMPs along slopes have not been maintained in a proper functioning condition to minimize erosion, degradation, and to stabilize the slopes; erosion, degradation and stabilization issues have persisted.

Inspector
Operator Name: CAE
Location



Photo 6: Photo taken from the northern interim areas of the Location. Photo example showing BMPs along slopes have not been maintained in a proper functioning condition to minimize erosion, degradation, and to stabilize the slopes; erosion, degradation and stabilization issues have persisted.

April 22, 2022
39.58887963N 108.06606628W

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335822



Photo 7: Photo taken from the stormwater diversion ditch along the north end of the Location. Photo shows Operator appears to have regraded to match the adjacent upslope areas. Photo shows that control measures to minimize erosion, degradation, and to stabilize the slopes of the ditch are missing or insufficient.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335822



Photo 8: Photo taken from the stormwater diversion ditch along the north end of the Location. Photo example showing BMPs along slopes are missing or insufficient to minimize erosion, degradation, and to stabilize the slopes of the ditch; erosion, degradation and stabilization issues have persisted.

Inspection
Operator Name: CAERU
Location I

Photo 9: Photo taken from the stormwater diversion ditch along the north end of the Location. Photo example showing BMPs along slopes are missing or insufficient to minimize erosion, degradation, and to stabilize the slopes of the ditch; erosion, degradation and stabilization issues have persisted.

