

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/22/2022

Submitted Date:

04/26/2022

Document Number:

696203600

FIELD INSPECTION FORMLoc ID 335594 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kirschner, Steven		steven.kirschner@state.co.us	
,		COGCC.inspections@caerus oilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335594	LOCATION	AC			-	N.PARACHUTE-65S95W 29SENE	RI

General Comment:

On 4/22/2022, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Caerus Piceance's N. Parachute-65S95W 29SENE location in Garfield County, Colorado.

This inspection is a followup to 696202450 dated 3/9/2021 to document compliance with the following corrective actions:

- 1003 Interim reclamation
- 1002.f Stormwater

Per Hearing Order No. 1-258, the Commission granted Caerus a waiver to comply with interim reclamation requirements of Rule 1003; corrective action from inspection 696202450 requiring compliance with 1003 Rules is no longer applicable

Per Hearing Order No. 1-258, The Commission's grant of a waiver of further compliance with Rule 1003 does not relieve Caerus of its obligation to control stormwater in accordance with Rule 1002.f.

This inspection is also in response to Resolution No. 402983947 stating corrective actions to comply with Rule 1002.f have been completed.

The following compliance issues were observed during this inspection:

- 1002.f

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [FIRR #402983947](#) states "Slopes were seeded and mulched to address vegetation on the slope".

It was observed in this inspection that control measures to minimize erosion, degradation, and to stabilize the slopes on the north end of the Location are missing or insufficient; control measures previously applied (hydromulch) have not been maintained in a proper functioning condition by Operator, and is no longer adequate; erosion, degradation and stabilization issues at the slopes have persisted.

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 05/06/2022

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696203601	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735962