

Inspection Photos  
Operator: Simcoe  
API: 067-06921  
Date: 4/26/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southwestern project area from the northwestern corner facing southeastward. Revegetation is progressing with smooth brome (*Bromus inermis*), western wheatgrass (*Pascopyrum smithii*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the northwestern project area facing eastward. Straw blanket needs maintenance.



Photo 4. View of the reference area comprised of ponderosa pine forest with gambel oak (*Quercus gambelii*), Oregon grape (*Mahonia repens*), and Idaho fescue (*Festuca idahoensis*).