

Inspection Photos  
Operator: Simcoe  
API: 067-07060  
Date: 4/26/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with smooth brome (*Bromus inermis*), western wheatgrass (*Pascopyrum smithii*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of erosional rilling where concentrated stormwater flows off of the edge of the working area.



Photo 4. View of the western project area facing northward.



Photo 5. View of the reference area comprised of ponderosa pine forest with gambel oak (*Quercus gambelii*), Oregon grape (*Mahonia repens*), and Idaho fescue (*Festuca idahoensis*).