

Inspection Photos
Operator: Simcoe
API: 067-08991
Date: 4/26/2022



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with smooth brome (*Bromus inermis*), western wheatgrass (*Pascopyrum smithii*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of cobble BMP within the northeastern project area that is full of sediment and needs maintenance.



Photo 4. View of the northern project area facing westward.



Photo 5. View of the reference area comprised of ponderosa pine forest with gambel oak (*Quercus gambelii*), Oregon grape (*Mahonia repens*), and Idaho fescue (*Festuca idahoensis*).