

Inspection Photos

API: 061-06287

Operator: CHEMCO INC

Inspection Date: 4/25/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06287
Date: 4/25/2022

Inspection Photos



Photo 1. Facing toward the tank battery. The area inside the berm needs to be kept free of vegetation. The fence around the tank needs to be repaired to prevent livestock entry. The berm around the tank needs to be rebuilt to contain a spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06287 Date: 4/25/2022

Inspection Photos



Photo 2. Facing toward the well site.



Inspection Photos



Photo 3. Facing west at the north side of the location. This is the area of impacted soils previously identified. A form 27 has been submitted for remediation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06287 Date: 4/25/2022

Inspection Photos



Photo 4. Facing east at the north side of the location. This is the area of impacted soils previously identified. A form 27 has been submitted for remediation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06287 Date: 4/25/2022

Inspection Photos



Photo 5. Facing northeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06287 Date: 4/25/2022

Inspection Photos



Photo 6. This flowline had previously leaked.



Photo 7. The impacted soils need to be cleaned up and the pipe inspected.

