

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2022

Submitted Date:

04/27/2022

Document Number:

690103004**FIELD INSPECTION FORM**Loc ID 320008 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspections@gwogco.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202244	WELL	SI	09/01/2020	GW	001-07649	GRANT PROPERTIES LTD. 1	PA
320008	LOCATION	AC			-	GGREAT WESTERN GRANT PROP	EG

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 202244 Type: WELL API Number: 001-07649 Status: SI Insp. Status: PA

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Grant Properties LTD 1) has been plugged and abandoned; cut and cap operations have been completed. COGCC form 42 notice of start of plugging operations doc #403002639 received 04/04/2022. The wellhead flowline (on location) has been removed. The on location dump and process flowlines at facility/ battery have been removed. No flowline risers were observed at the (PA) wellhead or facility/ battery areas. The facility/ tank battery has been decommissioned; tanks and equipment are being removed. No GWOC were on location at the time of inspection.

Corrective Action:

Date:

Facility ID: 320008 Type: LOCATION API Number: - Status: AC Insp. Status: EG

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690103005	View of location; looking N	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5737183