

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2022

Submitted Date:

04/26/2022

Document Number:

699804417

**FIELD INSPECTION FORM**

Loc ID 324192 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: PO BOX 370  
 City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263279	WELL	PR	08/30/2002	OW	045-08116	PA 24-26	PR

**General Comment:**

[COGCC Inspection Report Summary](#)  
 On Thursday 4/21/22 at approximately 14:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC PA-66S95W /26SESW. Location #324192 in Garfield County Colorado.  
 Refer to Document #699803985 inspection conducted on 1/7/22.  
 While there, I observed normal production operations.  
 This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment:

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>		corrective date
Type: Bradenhead	# 1	
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.	

Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 263279 Type: WELL API Number: 045-08116 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
		Berms				
		Compaction				
Sediment Traps						
		Ditches				
Berms						
Compaction						
		Sediment Traps				
Gravel						
		Culverts				
Ditches						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<span style="color: blue;">Refer to Storm water for corrective actions</span>	depaoloc	04/26/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804418	Photos for Insp. #699804417	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5736956">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5736956</a>