

<b>FORM</b> <b>INSP</b> Rev X/20	<b>State of Colorado</b> <b>Oil and Gas Conservation Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		Inspection Date: <u>04/27/2022</u> Submitted Date: <u>04/29/2022</u> Document Number: <u>691201604</u>
<b>FIELD INSPECTION FORM</b>			

Loc ID 327165 Inspector Name: Graber, Candice (Nikki) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments  
 1 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 47120  
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
 Address: P O BOX 173779  
 City: DENVER State: CO Zip: 80217-

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hamilton, Greg		Gregory_Hamilton@oxy.com	
,		COGCCInspections@Oxy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246453	WELL	PA	11/07/2014	GW	123-14250	BUFFALO GARDENS U 13-4J	EI
481346	SPILL OR RELEASE	AC	01/03/2022		-	Buffalo Gardens U #13-4J Historic	EI

**General Comment:**

This is an environmental inspection to document current site conditions at Remediation Project 22660 in response to Complaints 403009272 and 403027565. Any corrective actions from previous inspections as well as Form 19 or Form 27 conditions of approval are still applicable.

COGCC contacted the Operator (Oxy) environmental project manager who met with staff on location at approximately 11am. Operator had a crew working to better secure the location at the time of arrival. The remediation consisted of two excavations exposing groundwater. Both excavations were fenced with a combination of cattle panels and snow fence; both were netted for avian protection. Two unsigned stockpiles were present south of the excavation; Operator indicated they were clean backfill.

Per Operator, kids had recently entered the gated location and were seen playing in the area. In response, Operator repaired and strengthened the snow fence, secured the access gates with twine, and completely surrounded both excavations with caution tape. Per Operator, signage will be added to clean stockpiles.

Operator environmental project manager walked COGCC staff through the remediation progress and discussed potential next steps. Impacts are present at both locations and lab delays have slowed the remediation progress. COGCC agreed to a partial backfill of cleared sidewalls due to the sensitive nature of the site.

Additional work can be tracked under Remediation Project #22660.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Two unsigned stockpiles were present south of the excavation; Operator indicated they were clean backfill.		
Corrective Action:	Install signage.		Date: 05/02/2022

Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Excavation fencing was present however during inspection Operator fortified the fence and added caution tape.		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 246453 Type: WELL API Number: 123-14250 Status: PA Insp. Status: EI

Facility ID: 481346 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Adequate		
Comment	No E&P waste was present on location.			
Corrective Action				Date:

**Spill/Remediation:**

Comment:	Additional excavtion can be tracked under Remediation Project #22660.		
Corrective Action:			Date: _____

Emission Control Burner (ECB):	_____
Comment:	
Pilot:	_____ Wildlife Protection Devices (fired vessels): _____

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201605	Location Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739093">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739093</a>
691201606	Location Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739094">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739094</a>
691201607	Location Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739095">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739095</a>