

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2022

Submitted Date:

04/28/2022

Document Number:

696304141

FIELD INSPECTION FORMLoc ID 471794 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

17 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476140	WELL	PR	07/01/2021	OW	123-51015	Fiscus Fed 2627-04H	PR
476141	WELL	PR	07/01/2021	OW	123-51016	Fiscus Fed 2627-02H	PR
476142	WELL	PR	07/01/2021	OW	123-51017	Fiscus Fed 2627-03H	PR
476143	WELL	PR	07/01/2021	OW	123-51018	Fiscus Fed 2627-01H	PR
476144	WELL	PR	07/01/2021	OW	123-51019	Fiscus Fed 2627-05H	PR

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	03H, 04H and 05H missing Wellhead Signs; see photos		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/30/2022
Type	TANK LABELS/PLACARDS		
Comment:	ECD Knockout Tank missing Labels - NFPA, Content and Capacity. East Side of Tanks - Second Tank from the North missing Content and Capacity Labels See photos		
Corrective Action:	Comply with Rule 606	Date:	05/30/2022
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused Celler Gaurds on South end of Location; see photos		
Corrective Action:	Comply with Rule 606	Date:	05/30/2022
Type	UNUSED EQUIPMENT		
Comment:	Unmarked Riser at the North end of the Tank Berm; see photos		
Corrective Action:	Comply with Rule 606	Date:	05/06/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire Fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 3		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 11		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 2		
Comment:			
Corrective Action:		Date:	
Type: VRU	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:	Date:			

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	8	400 BBLS	STEEL AST		40.724040,-103.837730	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	476140	Type:	WELL	API Number:	123-51015	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	476141	Type:	WELL	API Number:	123-51016	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	476142	Type:	WELL	API Number:	123-51017	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	476143	Type:	WELL	API Number:	123-51018	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	476144	Type:	WELL	API Number:	123-51019	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding						
Silt Fences	Fail					
Gravel		Gravel				
Retention Ponds						
Culverts						
Ditches						

Comment: Silt Fence on South Side of Location is in Disrepair; see photosCorrective Action: Properly remove or repair/maintain Silt Fence per 1002.f Rule

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Tanks missing Labels, Unmarked Risers at Tank Berm. 03, 04, 05 Wellheads missing Signs. Silt Fence on South Side of Location in disrepair. Cellar Covers on South Side of Location.	petrie	04/28/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696304142	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739305