



Inspection Photos

081-07096

Inspection Date: 4/26/2022

All Photos taken by Kris Neidel

Photo #1 Sign on location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
081-07096

Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #2 Pad surface, well in background.



Inspection Photos

081-07096

Inspection Date: 4/26/2022

All Photos taken by Kris Neidel

Photo #3 Electric sub panel.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

081-07096

Inspection Date: 4/26/2022

All Photos taken by Kris Neidel

Photo #4 apparent surface water diversion on pad. The length of the diversion was walked, including the discharge. No apparent hydrocarbon or salt impacts were observed on the surface.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
081-07096

Inspection Date: 4/26/2022
All Photos taken by Kris Neidel



Photo #5 wellhead, production flowlines and electric sub panel.



Inspection Photos

081-07096

Inspection Date: 4/26/2022

All Photos taken by Kris Neidel

Photo #6 production flow line an wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

081-07096

Inspection Date: 4/26/2022

All Photos taken by Kris Neidel

Photo #7 Flowline risers near main access road, wellhead fence can just barely be seen on the right side of photo (against sky).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources