

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2022

Submitted Date:

05/02/2022

Document Number:

699503923

FIELD INSPECTION FORM

 Loc ID 328412 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 70385Name of Operator: SMITH ENERGY CORPAddress: 12706 SHILOH RDCity: GREELEY State: CO Zip: 80631**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248161	WELL	SI	10/01/2018	GW	123-15959	UPRR-AMOCO 23-1-63 1 (OWP)	SI

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: [fabricated fencing](#)

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date: _____
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:				Date: _____
Type: Vertical Separator	# 1			
Comment:				
Corrective Action:				Date: _____
Type: Bradenhead	# 1			
Comment: plumbed to surface				
Corrective Action:				Date: _____
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date: _____
Type: Ancillary equipment	# 1			
Comment: automation				
Corrective Action:				Date: _____

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	Open Top		,
Comment:	Netting adequate 80 BBL				
Corrective Action:					Date: _____

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:	
Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 248161 Type: WELL API Number: 123-15959 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: In need of MIT

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: In need of annual bradenhead test.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>This is an orphan well inspection. Well is in need of MIT due to how long it has been shut in. Well is in need of annual bradenhead test. At time of inspection weather conditions were overcast, warm, calm.</u>	medinaj	05/02/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503924	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5741495