

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/03/2022

Submitted Date:

05/03/2022

Document Number:

702400392**FIELD INSPECTION FORM**Loc ID 311290 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240346	WELL	PR	07/01/2017	OW	123-08134	MORGAN UNIT A 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:	Date: _____		

Good Housekeeping:		
Type		
Comment:	there is active dirt work going on around the wellsite	
Corrective Action:		Date:

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:		
Type	PUMP JACK	
Comment:	fabricated steel pipe	
Corrective Action:		Date:

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric panel, meter box and transformers		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:		
Yes/No	NO	
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240346 Type: WELL API Number: 123-08134 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 09/01/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 5-3-2022 at approximately 1400 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: KP Kauffman</p> <p>Location name: Morgan Unit A 1</p> <p>API #05-123-08134</p> <p>County: Weld</p> <p>Weather: overcast and cool.</p> <p>Location: dry</p> <p>While there, I observed a wellsite, PR at the time of inspection. Active Dirt work on location, Form 19 Doc #s 402843511 10-15-2021, 402848550 10-21-21 and 402996728 3-28-2022.</p> <p>During this inspection, I observed no compliance issues:</p> <p>This is a field inspection, any corrective actions from previous inspections that have not been addressed are still applicable.</p> <p>See attached photos.</p> <p>No follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	05/03/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400393	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5742815