

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2022

Submitted Date:

04/27/2022

Document Number:

690202828**FIELD INSPECTION FORM**Loc ID 324802 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 16520Name of Operator: CHEMCO INCAddress: 6970 SOUTH HOLLY CIR STE 206City: CENTENNIAL State: CO Zip: 80112**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neher, Morgan		morgan@chemco-og.com	
Neher, Gray		gh.neher@chemco-og.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150396	UIC DISPOSAL	AC	01/05/1996		-	WEAR*H C 3-1	RI

**General Comment:**

This a follow up inspection was performed at the Wear #3-1 Tank Battery Site.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Sign reinstalled.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	Leak at tank repaired.		
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:	There is various unused unnecessary equipment/supplies being stored at the location. All supplies not necessary for use on the location is prohibited.		
Corrective Action:	Comply with Rule 606	Date:	01/28/2022
Type	OTHER		
Comment:	The electric utility box was closed and wired. The electric line remains exposed on the ground and needs to be protected.		
Corrective Action:	Comply with 602 SAFETY REQUIREMENTS.	Date:	01/14/2022
Type	OTHER		
Comment:	There is a barrel onsite that contains burnt ashes which indicates burning onsite which was also observed in a previous inspection. No trash, waste, rubbish, or other materials will be burned or buried at an Oil and Gas Location.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Truck Loadout			
Comment:	There is still oily waste at the load out area that needs to be cleaned up.			
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.			Date: 01/28/2022

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:					Date:	

**Paint**

Inspector Name: COSTA, RYAN

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	The berms around the tank battery has been built up better to contain a spill.			
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403029844	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5737045">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5737045</a>
690202829	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5737037">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5737037</a>