

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2022

Submitted Date:

04/27/2022

Document Number:

699804423**FIELD INSPECTION FORM**Loc ID 334869 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211300	WELL	PR	11/10/1998	GW	045-07059	UNOCAL GM 24-2	PR
272034	WELL	PR	02/11/2005	GW	045-10010	AMERICAN SODA GM 424-2	PR
272088	WELL	PR	02/18/2005	GW	045-10020	AMERICAN SODA GM 524-2	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 4/26/22 at approximately 12:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2SESW. Location #334869 in Garfield County Colorado.

Refer to document #699804162 inspection conducted on 2/16/22. All previous corrective actions have been completed.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Loadline open ended with a corrective action date of 5/4/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 4		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Loadline open ended.		
Corrective Action:	loadlines will be bullplugged or capped.		Date: 05/04/2022
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: <u>211300</u>	Type: <u>WELL</u>	API Number: <u>045-07059</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<u>Producing Well</u>			
Comment:	<u>Producing</u>		
Corrective Action:		Date:	
Facility ID: <u>272034</u>	Type: <u>WELL</u>	API Number: <u>045-10010</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<u>Producing Well</u>			
Comment:	<u>Producing</u>		
Corrective Action:		Date:	
Facility ID: <u>272088</u>	Type: <u>WELL</u>	API Number: <u>045-10020</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<u>Producing Well</u>			
Comment:	<u>Producing</u>		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Berms				
		Gravel				
Sediment Traps						
Ditches						
Berms						
		Culverts				
Compaction						
		Compaction				
		Ditches				
		Sediment Traps				
Gravel						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Equipment for corrective actions.	depaoloc	04/27/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403029773	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5736965
699804424	Photos for Insp. #699804423	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5736959