

Inspection Photos

ID: 412161

Operator: WAPITI OPERATING LLC

Inspection Date: 5/3/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast. There has been recent disturbance along the gathering pipeline at Lat/Long:37.05440,-104.76614.This area needs to be reclaimed and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:412161 | Date: 5/3/2022

Inspection Photos



Photo 2. Facing southwest along the pipeline disturbance. The disturbed soils are susceptible to erosion and need to be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:412161 | Date: 5/3/2022

Inspection Photos



Photo 3. Facing southwest along the pipeline disturbance. The disturbed soils are susceptible to erosion and need to be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:412161 | Date: 5/3/2022

Inspection Photos



Photo 4. Facing toward the VPRC CENTRAL FACILITY UNIT C-3.

