

Inspection Photos

API: 071-09838

Operator: WAPITI OPERATING LLC

Inspection Date: 5/3/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 5/3/2022

Inspection Photos



Photo 1. The culvert outlet is eroded and has not been repaired. No culvert outlet protection installed. Lat/Long:37.02423,-104.82919
Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 5/3/2022

Inspection Photos



Photo 2. Facing southwest along the main road near the well site. Stormwater has washed across the road causing erosion. The culvert is filled in with sediment and has not been repaired. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 5/3/2022

Inspection Photos



Photo 3. Facing toward the northeast side of the location. The area on the right side of the photo is not stabilized or revegetated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 5/3/2022

Inspection Photos




Photo 4. Facing toward the northeast side of the location. This area is not stabilized and there is an erosion. The wattles are degraded shown at red arrow. Previous corrective action not completed. There are noxious weeds beginning to grow (Yellow arrow – Musk thistle)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 5/3/2022

Inspection Photos



Photo 5. Facing toward the northeast side of the location. This area is not stabilized and there is an erosion channel that will need to be repaired. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 5/3/2022