

# Inspection Photos

API: 071-07915

Operator: WAPITI OPERATING LLC

Inspection Date: 5/3/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07915 | Date: 5/3/2022

## Inspection Photos



**Photo 1.** Facing west toward the access road ascending the hillside. The road has been graded. The culvert inlet shown at red arrow is filled in with sediment. The culvert outlet is shown in photo 2.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 5/3/2022



## Inspection Photos



**Photo 2.** The culvert outlet is eroded and does not have outlet protection. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 5/3/2022



## Inspection Photos



**Photo 3.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 5/3/2022



## Inspection Photos



**Photo 4.** There are noxious weeds sprouting up along the cut slope at the location which will need to be controlled. (Hounds tongue).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 5/3/2022