

# Inspection Photos

API: 071-08769

Operator: WAPITI OPERATING LLC

Inspection Date: 5/3/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 5/3/2022

## Inspection Photos



**Photo 1.** Facing southeast along the main road at the upper part of Lorencito Canyon. There is erosion along the road from recent storm event. Stormwater is bypassing the culvert. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 5/3/2022

## Inspection Photos



**Photo 2.** The culvert along the road is filled in with sediment causing stormwater to flow down the side of the road. Lat/Long:37.00581,-104.83861. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 5/3/2022

## Inspection Photos



**Photo 3.** The culvert along the road is filled in with sediment causing stormwater to flow down the side of the road. Lat/Long:37.00499,-104.83742. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 5/3/2022

## Inspection Photos



**Photo 4.** There is an erosion gully along the road that needs to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 5/3/2022

## Inspection Photos



**Photo 5.** The side of the road is eroded and is not stabilized at Lat/Long:36.99952,-104.83425. This area or erosion needs to be repaired and stabilized. Previous corrective action not completed. Red arrow points to 4.5 ft. shovel.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 5/3/2022

## Inspection Photos



**Photo 6.** The side of the road is eroded and not stabilized at Lat/Long:36.99952,-104.83425. Erosion head cutting is continuing to occur further back. This area needs to be repaired and stabilized. Previous corrective action not completed. Red arrow points to 4.5 ft. shovel.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 5/3/2022

## Inspection Photos



**Photo 7.** There was grading performed along the road. The disturbance along the side of the road needs to be seeded and reclaimed. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 5/3/2022

## Inspection Photos



**Photo 8.** The culvert along the road is filled in with sediment at Lat/Long:36.99405,-104.84710. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 5/3/2022

## Inspection Photos



**Photo 9.** Facing northeast toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 5/3/2022

## Inspection Photos



**Photo 10.** There are noxious weeds sprouting up at the location which will need to be controlled. (Hounds tongue, Mullein).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 5/3/2022