

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/04/2022

Submitted Date:

05/04/2022

Document Number:

687400839

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Huck, Keith On-Site Inspection    
 319715 \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 74165   
 Name of Operator: RENEGADE OIL & GAS COMPANY LLC   
 Address: 6155 S MAIN STREET #225   
 City: AURORA State: CO Zip: 80016

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments   
1 Number of Corrective Actions   
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Espinosa, Bill		billespinosa30@yahoo.com	
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201079	WELL	PR	08/20/2008	OW	001-06482	FERGUSON 1-25	PR

**General Comment:**

*(This area is currently blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

Type WELLHEAD

Comment: Adequate

Corrective Action:

Date:

**Emergency Contact Number:**

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type UNUSED EQUIPMENT

Comment: Unused Chemical Tank north of pupmjack. Also old rags and stainless tubing sitting on pumpjack skid. See Attached picture

Corrective Action: Comply with Rule 606

Date: 05/19/2022

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Deadman # & Marked # 4

Comment:

Corrective Action:

Date:

Type: Bradenhead # 1

Comment: Appears to be plumbed to surface

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 201079 Type: WELL API Number: 001-06482 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/30/2021 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On (Wednesday) (05/04/2022) at approximately (10:00am), I, Inspector (Keith Huck), conducted an on-site inspection at (Ferguson#1) (Renegade Oil and Gas Company LLC), at (Location#319715) in (Adams,County) Colorado.                      While there, I observed a Production Facility</p> <p>During this inspection the following possible compliance issues were observed:                      Unused Chemical Tank north of pupmjack. Also old rags and stainless tubing sitting on pumpjack skid.                      See Attached picture. Comply with Rule 606</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	huckk	05/04/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687400840	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5744197">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5744197</a>