

Inspection Photos

API: 071-06867

Operator: WAPITI OPERATING LLC

Inspection Date: 5/3/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06867 | Date: 5/3/2022

Inspection Photos



Photo 1. Facing southeast toward the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06867 | Date: 5/3/2022

Inspection Photos



Photo 2. There are areas along the east side that could use additional hand seeding to establish vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06867 | Date: 5/3/2022

Inspection Photos



Photo 3. Facing west at the location. There are rock check dams installed where erosion was occurring. This area could use additional hand seeding to establish vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06867 | Date: 5/3/2022

Inspection Photos



Photo 4. Facing northeast at the location. This area could use additional hand seeding to establish vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06867 | Date: 5/3/2022

Inspection Photos



Photo 5. Facing southwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06867 | Date: 5/3/2022