

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/28/2022

Submitted Date:

05/04/2022

Document Number:

701004970

FIELD INSPECTION FORM

Loc ID 321069 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 76859
Name of Operator: SCHREIDER & COMPANY INC
Address: 9227 E LINCOLN AVE SUITE 200
City: LONE TREE State: CO Zip: 80124

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kelly, George	(602) 697-2484	schreiderco@outlook.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205951	WELL	PR	08/01/2017	GW	009-06366	STATE 1-17	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Trail through farm ground		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to meter run door and laying on the ground. Reinstall lease sign where visible		
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	There is some debris laying around that needs removed from location		
Corrective Action:			Date:
Type	STORAGE OF SUPL		
Comment:	Unit and sulfatreat separator stored on location. Remove unused equipment from location		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	American unit removed from wellhead. Remove unused equipment from location		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	North side of wellhead		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator next to meter run		
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 205951 Type: WELL API Number: 009-06366 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Downhole equipment still in wellbore. Unit removed from wellhead](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Other	Pass			

Comment: [Access is farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701005032	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5745172