

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2022

Submitted Date:

04/29/2022

Document Number:

691201604

FIELD INSPECTION FORMLoc ID 327165 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	All Inspections
Hamilton, Greg		Gregory_Hamilton@oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246453	WELL	PA	11/07/2014	GW	123-14250	BUFFALO GARDENS U 13-4J	EI
481346	SPILL OR RELEASE	AC	01/03/2022		-	Buffalo Gardens U #13-4J Historic	EI

General Comment:

This is an environmental inspection to document current site conditions at Remediation Project 22660 in response to Complaints 403009272 and 403027565. Any corrective actions from previous inspections as well as Form 19 or Form 27 conditions of approval are still applicable.

COGCC contacted the Operator (Oxy) environmental project manager who met with staff on location at approximately 11am. Operator had a crew working to better secure the location at the time of arrival. The remediation consisted of two excavations exposing groundwater. Both excavations were fenced with a combination of cattle panels and snow fence; both were netted for avian protection. Two unsigned stockpiles were present south of the excavation; Operator indicated they were clean backfill.

Per Operator, kids had recently entered the gated location and were seen playing in the area. In response, Operator repaired and strengthened the snow fence, secured the access gates with twine, and completely surrounded both excavations with caution tape. Per Operator, signage will be added to clean stockpiles.

Operator environmental project manager walked COGCC staff through the remediation progress and discussed potential next steps. Impacts are present at both locations and lab delays have slowed the remediation progress. COGCC agreed to a partial backfill of cleared sidewalls due to the sensitive nature of the site.

Additional work can be tracked under Remediation Project #22660.

LocationOverall Good: ☒**Signs/Marker:**

Type OTHER

Comment: Two unsigned stockpiles were present south of the excavation; Operator indicated they were clean backfill.

Corrective Action: Install signage.

Date: 05/02/2022

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type OTHER

Comment: Excavation fencing was present however during inspection Operator fortified the fence and added caution tape.

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	<u>246453</u>	Type:	<u>WELL</u>	API Number:	<u>123-14250</u>	Status:	<u>PA</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>481346</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Adequate		
Comment	No E&P waste was present on location.			
Corrective Action				Date:

Spill/Remediation:

Comment:	Additional excavtion can be tracked under Remediation Project #22660.			
Corrective Action:				Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403032386	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739110
691201605	Location Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739093
691201606	Location Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739094
691201607	Location Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739095