

Inspection Photos
Operator: Enduring
API: 067-08398
Date: 4/29/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Vegetation remains sparse, similar to reference area. Continue monitoring and managing to ensure site stabilization and that weeds are controlled.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of the reference area comprised of open grass field.