

Inspection Photos
Operator: Enduring
API: 067-07759
Date: 4/29/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Vegetation remains sparse. Continue monitoring and managing to ensure site stabilization and that weeds are controlled.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of erosional channel approximately 12 inches wide and deep near the well pad entrance.



Photo 5. View of the southern project area from the southeastern corner facing westward.



Photo 6. View of BMPs no longer functioning, where stormwater diversion is forming an erosional channel south of the project area.



Photo 7. View of another BMP no longer functioning and not adequate in the southern project area.



Photo 8. View of the reference area comprised of pinyon and juniper woodland with antelope bitterbrush, gambel oak, Indian ricegrass, and sharpleaf twinpod.