

Inspection Photos  
Operator: Enduring  
API: 067-07514  
Date: 4/29/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is sparse, progressing in portions with western wheatgrass, other portions remain bare. Stabilization is needed here.





Photo 3. View of erosional rilling within the western project area. Stabilization is needed here.





Photo 4. View of erosional channel forming within the southwestern project area. Wattles are not functioning and are not adequate BMPs for this area.





Photo 5. View of more erosional channeling forming within the southwestern project area. Wattles are not functioning and are not adequate BMPs for this area.





Photo 6. View of the reference area comprised of pinyon and juniper woodland with antelope bitterbrush, sagebrush, gambel oak, western wheatgrass, Indian ricegrass, and Navajo tea.