

Inspection Photos  
Operator: Enduring  
API: 067-08667  
Date: 4/29/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the well pad entrance facing northward. Revegetation is progressing with smooth brome, intermediate wheatgrass, and western wheatgrass.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 3. View of weed debris observed within the project area.