

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/05/2022

Submitted Date:

05/06/2022

Document Number:

679604724

FIELD INSPECTION FORMLoc ID 330660 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251623	WELL	TA	01/01/2022	OW	123-19426	BASS N 14-10	TA

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	storage of equipment inside/outside gas meters and near ECDs. See attached photos.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	iron		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	wire		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:	east gas meter is not annually calibrated. See attached photo.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 06/05/2022
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	5	OTHER	BV CONCRETE		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	53 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with crude oil tanks.				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	6	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	251623	Type:	WELL	API Number:	123-19426	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder: EQUIPMENT PRESENT/DISCONNECTED									
Comment: <input type="text"/>									
Corrective Action: <input type="text"/>									
Date: <input type="text"/>									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>**Weather Conditions: sunny, muddy</p> <p>On Thursday, May 5, 2022 at approximately 12:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at BASS N 14-10 (Chevron), at location #: 330660 in WELD COUNTY Colorado.</p> <p>While there, I observed a shut in facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. Storage of equipment inside gas meter houses and disconnected/unused equipment outside gas meter houses. Comply with Rule 606. (Corrective Action Date: June 5, 2022) See attached photos #7-11.</p> <p>2. It appears the east gas meter is not annually calibrated. Calibrate gas metering equipment annually to comply with rule 430.d.(1). (Corrective Action Date: June 5, 2022) See attached photo #12.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	05/06/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679604725	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5746909