



**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:   
 Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
Comment:	iron		
Corrective Action:		Date:	

**Equipment:**

		# 1			corrective date
Type: Bradenhead					
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift		#			
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 300041 Type: WELL API Number: 123-29602 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
No corrective actions were observed at the time of inspection. **Weather Conditions: sunny, muddy	santistb	05/05/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679604723	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5746908">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5746908</a>