

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403040606

Date Received:  
05/06/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #225  
City: AURORA State: CO Zip: 80016  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
Ingve, Edward	(303) 829-2354	ed@renegadeoilandgas.com
JB Condill	(303) 680-4725	jbcrog@aol.com
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 687400837  
Inspection Date: 04/26/2022 FIR Submit Date: 04/29/2022 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: RENEGADE OIL & GAS COMPANY LLC Company Number: 74165  
Address: 6155 S MAIN STREET #225  
City: AURORA State: CO Zip: 80016

LOCATION - Location ID: 319884

Location Name: LINNEBUR-62S61W Number: 18SESE County: \_\_\_\_\_  
Qtrqtr: SESE Sec: 18 Twp: 2S Range: 61W Meridian: 6  
Latitude: 39.871260 Longitude: -104.246840

FACILITY - API Number: 05-001-00 Facility ID: 319884

Facility Name: LINNEBUR-62S61W Number: 18SESE  
Qtrqtr: SESE Sec: 18 Twp: 2S Range: 61W Meridian: 6  
Latitude: 39.871260 Longitude: -104.246840

CORRECTIVE ACTIONS:

1 CA# 161424

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

All loadlines will be bullplugged or capped. 603i

Date: 06/04/2022

Response: CA COMPLETED

Date of Completion: 05/03/2022

Operator Comment: Material added to eliminate gap underneath production tanks (see attached photo).  
Bull plugs added to loadlines (see attached photo).

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective item identified has been addressed. Facility services two shut in wells on the Third Creek Gas Gathering System and is not in use. All fluids have been removed from tanks and separator.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edward Ingve

Signed: \_\_\_\_\_

Title: Manager/Owner

Date: 5/6/2022 2:34:15 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403041055	Material added for tank bottom
403041076	Bull plugged load lines

Total Attach: 2 Files