

Inspection Photos

081-07349

Inspection Date: 5/5/2022

All Photos taken by Kris Neidel



Photo #1 sign at location. Well was PA wellhead was cut off. Surface of ground appeared to be backfilled.





Inspection Photos  
081-07349  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel

**Photo #2 area near wellhead, flowlines sill present**



Inspection Photos  
081-07349

Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel



Photo #3 sign at lower left was area of wellhead, note flowline marker in background.



Inspection Photos  
081-07349  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel

**Photo #4 photo taken from near wellhead, in center of photo, off location gathering lines.**





Inspection Photos  
081-07349  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel

**Photo #5 close up of Photo #4; gathering line and valve can. This area should be identified and investigated on the Form 27**





Inspection Photos  
081-07349  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel

**Photo #6 debris from PA and cut cap. All debris should be removed.**





Inspection Photos  
081-07349  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel

**Photo #7 photo of pad, showing bare ground.**



Inspection Photos  
081-07349  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel

**Photo #8 adjacent possibly surface water diversions?**





Inspection Photos  
081-07349  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel

**Photo #9 Pipeline infrastructure from Photo #4. there was a impoundment of some sort, looks similar to a pit but was open on the up grade side. This area should be addressed on the form 27.**



Inspection Photos  
081-07349  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel

Photo #10 another angle of photo #9

